

**Flood Control Project Maintenance**  
**2010 Channel Summary Report**  
**Overall Unit and Item Ratings**

**Adin Community Service District**

---

**Ash Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

**Dry Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

**Flood Control Project Maintenance**  
**2010 Channel Summary Report**  
**Overall Unit and Item Ratings**

## DWR Sutter Maintenance Yard

---

### Big Chico Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	U
	Encroachments	A

### Lindo Channel & Sandy Gulch & Sandy Gulch

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	M
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

### Little Chico Creek

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	M
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

**Flood Control Project Maintenance**  
**2010 Channel Summary Report**  
**Overall Unit and Item Ratings**

**Fairfield Suisun Sewer District**

---

**Laurel Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

**Ledgewood Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A
	Concrete Surfaces	A

**McCoy Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	M
	Encroachments	A

**Union Avenue Diversion**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

**Flood Control Project Maintenance**  
**2010 Channel Summary Report**  
**Overall Unit and Item Ratings**

---

**Madera County FCWCA**

---

**Ash Slough**

Overall Unit Rating	Rated Item	Item Rating
N	Channel Not Rated	

**Berenda Slough**

Overall Unit Rating	Rated Item	Item Rating
N	Channel Not Rated	

**Chowchilla River**

Overall Unit Rating	Rated Item	Item Rating
N	Channel Not Rated	

**Fresno River**

Overall Unit Rating	Rated Item	Item Rating
N	Channel Not Rated	

**Flood Control Project Maintenance**  
**2010 Channel Summary Report**  
**Overall Unit and Item Ratings**

## Merced Streams Group

### Bear Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M *</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M *
	Revetments	A
	Encroachments	A

\* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

### Black Rascal Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M *</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	M *

\* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

### Burns Creek

Overall Unit Rating	Rated Item	Item Rating
<b>U</b>	Vegetation & Obstructions	N
	Shoaling / Sedimentation	N
	Erosion / Bank Caving	N
	Revetments	N
	Encroachments	U

### Mariposa Creek & Duck Slough

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	N
	Encroachments	A

### Miles Creek

Overall Unit Rating	Rated Item	Item Rating
<b>N</b>	<b>Channel Not Rated</b>	

### Owens Creek

Overall Unit Rating	Rated Item	Item Rating
<b>N</b>	<b>Channel Not Rated</b>	

**Flood Control Project Maintenance**  
**2010 Channel Summary Report**  
**Overall Unit and Item Ratings**

## Placer County

---

### Truckee River

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

**Flood Control Project Maintenance**  
**2010 Channel Summary Report**  
**Overall Unit and Item Ratings**

## San Joaquin County Flood Control and Water Conservation District

---

### Duck Creek Diversion Channel

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

### North Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	N
	Encroachments	A

### South Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

### South Littlejohn Creek North Branch

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A

**Flood Control Project Maintenance**  
**2010 Channel Summary Report**  
**Overall Unit and Item Ratings**

---

**Tehama County Flood Control and Water Conservation District**

---

**McClure Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	N
	Encroachments	A

**Salt Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A